Oil Field Environmental Incident Summary

Responsible Party: Targa Resources

Well Operator: Well Name:

Field Name: Well File #:

Date Incident: 9/4/2015 Time Incident: 14:00 Facility ID Number:

County: MCKENZIE Twp: 151 Rng: 94 Sec: 5 Qtr

Location Description: From Riverview 3 pad head south down RTA pipeline easement

approximately 3/4 mile then head east to steep coulee (allotment 5-29).

Submitted By: Mitchell W. Anderson Received By:

Contact Person: David Low

1939 125th Avenue NW Watford City, ND 58854

General Land Use: Badlands Terrain Affected Medium: Topsoil

Distance Nearest Occupied Building:2 MileDistance Nearest Water Well:2 Mile

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 4 Barrels

Description of Other Released Contaminant:

Water and drilling mud (bentonite clay)

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There were no immediate health hazards associated with this release.

Areal Extent:

1"d x 40'W x 400'L

Potential Environmental Impacts:

There were no adverse environmental impacts to any surface waters or groundwater as a result from this release.

Action Taken or Planned:

Silt fences and waddles were installed immediately upon discovery to prevent gravity flow downslope.

Wastes Disposal Location: Recovered wastes will be transported to a licensed landfill.

Agencies Involved: Bureau of Indian Affairs

Updates

Date: 9/10/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

This incident has been reported earlier in the General incident form #3902. It is on MHA Nation property and the report has been forwarded to the MHA, BIA and EPA. No further followup necessary on this report.